



LEGEND

- 1 Existing Driveway Widened to Two-Way Ingress/Egress
- 2 Renovated Parking Lot Increases to (3) ADA and (35) Standard Spaces
- 3 Park Entry Plaza with Additive Alternate: Seatwalls
- 4 Re-Routed Jogging/Park Path with New Resilient Surfacing
- 5 Additive Alternate: New Perimeter Tube Steel Fence along W Oakey Blvd with Gates at Each Driveway Entrance
- 6 Existing Sport Court
- 7 Additive Alternate: New Steel Shade Arbor with Benches
- 8 Existing Landscape to Remain. Additive Alternate: Bare Areas Enhanced with New Trees and Shrubs
- 9 Existing Jogging/Park Path to Remain - New Resilient Surfacing and New Path Lighting
- 10 New Park Entry Plaza with Additive Alternate: Seatwalls at Corners. Also Serves as Park Maintenance Access.
- 11 New Plaque on Pedestal in Planter Honoring 'Bob Baskin'
- 12 Benches around Splash Pad
- 13 New Splash Pad
- 14 New Restroom Building
- 15 New Exercise Station with Relocated Equipment
- 16 Picnic Table on Compacted Native Ground
- 17 Existing Turf Area to Remain
- 18 Additive Alternate: Seatwall / Planters
- 19 Group Shelter with (2) Tables
- 20 Additive Alternate: Existing Splash Pad Whale Retired into a Sculpture in Planter Refreshed with New Paint
- 21 Additive Alternate: New Fabric Shade Canopy
- 22 Existing Play Area with New Safety Surfacing and Additional New Play Elements
- 23 Existing Exercise Station Widened with New Equipment Total (2)
- 24 Additive Alternate: New 5-12 Shaded Play Area with Modern Kinetic Play
- 25 Existing Turf Area Enhanced with Soft Berms to Remain
- 26 New 3-FT Wide DG Strip with Concrete Header For Irrigation Setback to Help Protect Track Surfacing
- 27 Additive Alternate: Salvage (4) Existing Picnic Shelters with Tables, Restore Them And Reinstall to New Location.
- 28 Relocated Picnic Table Station Positioned Around Pathway
- 29 Tube Steel Safety Fencing at Splash Pad

